

FIG. 1

2/46




FIG.2

3/46




FIG.3

4/46




FIG.4



6/46




FIG.6

7 / 4 6




FIG.7

8/46




FIG.8

9 / 4 6




FIG.9

10 / 46




FIG.10

11/46




FIG.11

12/46




FIG.12

1 3 / 4 6




FIG.13

14/46




FIG.14

15 / 46




FIG.15

16/46




FIG.16

17 / 46




FIG.17

18/46




FIG.18

19 / 46





FIG.19

20 / 46



21/46




FIG.21

22 / 46




FIG.22

23/46





FIG.23

24 / 46



25/46




FIG.25

26 / 46




FIG. 26

27/46




FIG.27

28 / 46




FIG.28

29 / 46




FIG.29



3 1 / 4 6




FIG.31




FIG. 32

3 3 / 4 6

i 2j - i		
0	0	1
1	-1	$r \sin(t)$
1	1	$\cos(t) r$
2	-2	$r^2 \sin(2 t)$
2	0	$2 r^2 - 1$
2	2	$r^2 \cos(2 t)$
3	-3	$r^3 \sin(3 t)$
3	-1	$(3 r^3 - 2 r) \sin(t)$
3	1	$(3 r^3 - 2 r) \cos(t)$
3	3	$r^3 \cos(3 t)$
4	-4	$r^4 \sin(4 t)$
4	-2	$(4 r^4 - 3 r^2) \sin(2 t)$
4	0	$6 r^4 - 6 r^2 + 1$
4	2	$(4 r^4 - 3 r^2) \cos(2 t)$
4	4	$r^4 \cos(4 t)$
5	-5	$r^5 \sin(5 t)$
5	-3	$(5 r^5 - 4 r^3) \sin(3 t)$
5	-1	$(10 r^5 - 12 r^3 + 3 r) \sin(t)$
5	1	$(10 r^5 - 12 r^3 + 3 r) \cos(t)$
5	3	$(5 r^5 - 4 r^3) \cos(3 t)$
5	5	$r^5 \cos(5 t)$
6	-6	$r^6 \sin(6 t)$
6	-4	$(6 r^6 - 5 r^4) \sin(4 t)$
6	-2	$(15 r^6 - 20 r^4 + 6 r^2) \sin(2 t)$
6	0	$20 r^6 - 30 r^4 + 12 r^2 - 1$
6	2	$(15 r^6 - 20 r^4 + 6 r^2) \cos(2 t)$
6	4	$(6 r^6 - 5 r^4) \cos(4 t)$
6	6	$r^6 \cos(6 t)$

FIG.33

3 4 / 4 6

i 2j - i		
0	0	1
1	-1	y
1	1	x
2	-2	2 y x
2	0	2 x ² + 2 y ² - 1
2	2	x ² - y ²
3	-3	3 y x ² - y ³
3	-1	3 y x ² + 3 y ³ - 2 y
3	1	3 x ³ + 3 x y ² - 2 x
3	3	x ³ - 3 x y ²
4	-4	4 y x ³ - 4 y ³ x
4	-2	8 y x ³ + 8 y ³ x - 6 y x
4	0	6 x ⁴ + 12 x ² y ² + 6 y ⁴ - 6 x ² - 6 y ² + 1
4	2	4 x ⁴ - 4 y ⁴ - 3 x ² + 3 y ²
4	4	x ⁴ - 6 x ² y ² + y ⁴
5	-5	5 y x ⁴ - 10 y ³ x ² + y ⁵
5	-3	15 y x ⁴ + 10 y ³ x ² - 5 y ⁵ - 12 y x ² + 4 y ³
5	-1	10 y x ⁴ + 20 y ³ x ² + 10 y ⁵ - 12 y x ² - 12 y ³ + 3 y
5	1	10 x ⁵ + 20 x ³ y ² + 10 x y ⁴ - 12 x ³ - 12 x y ² + 3 x
5	3	5 x ⁵ - 10 x ³ y ² - 15 x y ⁴ - 4 x ³ + 12 x y ²
5	5	x ⁵ - 10 x ³ y ² + 5 x y ⁴
6	-6	6 y x ⁵ - 20 y ³ x ³ + 6 y ⁵ x
6	-4	24 y x ⁵ - 24 y ⁵ x - 20 y x ³ + 20 y ³ x
6	-2	30 y x ⁵ + 60 y ³ x ³ + 30 y ⁵ x - 40 y x ³ - 40 y ³ x + 12 y x
6	0	20 x ⁶ + 60 x ⁴ y ² + 60 x ² y ⁴ + 20 y ⁶ - 30 x ⁴ - 60 x ² y ² - 30 y ⁴ + 12 x ² + 12 y ² - 1
6	2	15 x ⁶ + 15 x ⁴ y ² - 15 x ² y ⁴ - 15 y ⁶ - 20 x ⁴ + 20 y ⁴ + 6 x ² - 6 y ²
6	4	6 x ⁶ - 30 x ⁴ y ² - 30 x ² y ⁴ + 6 y ⁶ - 5 x ⁴ + 30 x ² y ² - 5 y ⁴
6	6	x ⁶ - 15 x ⁴ y ² + 15 x ² y ⁴ - y ⁶

FIG.34




FIG. 35

3 6 / 4 6




FIG.36

37 / 46





FIG.37

3 8 / 4 6



39/46




FIG.39

40 / 46





FIG. 40

4 1 / 4 6



42 / 46




FIG. 42

4 3 / 4 6




FIG. 43

44 / 46




FIG. 44

45 / 46




FIG.45




FIG.46